HDO922 SOFTWARE RELEASE HISTORY

General

Minimum recommended software version: 1.0

Software update methods:

− **Local update**: CATVisor Commander 2.9 or later, 19200 bps HDO/DVX bus connection through HDO rack with HDX021 or DVX021 cable. Typical update time 2 min.

− **Remote update**: CATVisor Commander 2.9 or later, IP connection through HDC100. Typical update time 3 min.

LATEST VERSION

Version 1.2, released 8.6.2021 – Minor bug fixes

Compatibility

Compatible with all HDO922 hardware versions.

Field upgradeable to all previous software versions.

All required viewer files are included in DUS100 package version 5.17 or later.

Fixes

− Added some hysteresis and delay to laser "Auto" mode. (Shout 38761)

− Fixed: "Adjustment near limits" alarm does not always activate correctly. (Shout 38752)

− Fixed: Brief signal level changes can appear after reset. (Shout 38753)

− Internal changes not visible to end-user. (Shout 34288)

OLDER VERSIONS

Version 1.0, released 19.2.2020 – First customer release

Compatibility

Compatible with all HDO922 hardware versions.

Field upgradeable to all previous software versions.