

HDO613 SOFTWARE RELEASE HISTORY

General

Minimum recommended software version: 1.4

Software update methods:

- **Local update:** CATVisor Commander, 19200 bps DVX bus connection through HDO rack with HDX021 or DVX021 cable. Typical update time 2 min.
- **Remote update:** CATVisor Commander, IP connection through HDC100. Typical update time 3 min.

LATEST VERSION

Version 1.7, released 6.10.2016 – Manufacturability enhancement

Compatibility

Compatible with all HDO613 hardware versions.

Field upgradeable to all previous software versions.

All required viewer files are included in DUS100 package version 4.42 or later.

Enhancements

- Improved spectrum analyser manufacturability. (Shout 30478)

OLDER VERSIONS

Version 1.4, released 24.5.2016 – Major bug fix and spectrum analyser support

Compatibility

Compatible with all HDO613 hardware versions.

Field upgradeable to all previous software versions.

Enhancements

- Added support for spectrum analyser option.

Fixes

- Fixed: Additional random data may be sometimes written to non-volatile memory when new settings are entered by the user. This may cause loss of calibration data or incorrect parameter values in some units. HDO613 units with spectrum analyser option are not affected by this issue. (Shout 29940)

Version 1.2, released 19.2.2016 – Major bug fix

Compatibility

Compatible with all HDO613 hardware versions.

Field upgradeable to all previous software versions.

Fixes

- Fixed: Unit appears at wrong address (one rack too low) when rack address is set to higher value (~6...15). (Shout 29285)

Version 1.0, released 14.10.2015 – First customer release

Compatibility

Compatible with all HDO613 hardware versions.