

HDO907 SOFTWARE RELEASE HISTORY

General

Minimum recommended software version: 1.0 for hardware version A
2.4 for hardware version B and above

Software update methods:

- **Local update:** CATVisor Commander 2.9 or later, 19200 bps HDO/DVX bus connection through HDO rack with HDX021 or DVX021 cable. Typical update time 2 min.
- **Remote update:** CATVisor Commander 2.9 or later, IP connection through HDC100. Typical update time 3 min.

LATEST VERSION

Version 2.7, released 13.12.2017 – Hardware version C support and minor bug fixes

Compatibility

Compatible only with HDO907 hardware versions B and C.

Field upgradeable to 2.x software versions.

All required viewer files are included in DUS100 package version 4.46 or later.

Enhancements

- Added support for new hardware version C. (Shout 33913)
- ALSC can be disabled from one input by setting pilots to 0 Hz. Previously this caused “All pilots missing” alarm. (Shout 31037)

Fixes

- Fixed: Laser does not always start after software update. (Shout 33800)

OLDER VERSIONS

Version 2.4, released 18.2.2016 – Hardware version B and spectrum analyser support

Compatibility

Compatible only with HDO907 hardware version B.

Field upgradeable to 2.x software versions.

Enhancements

- Added support for new hardware version B. Version A is not supported.
- Added support for spectrum analyser option. (Shout 29243, 29271)
- Added “Laser off” alarm. (Shout 28995)

Version 1.2, released 16.3.2015 – Enhancements

Compatibility

Compatible only with HDO907 hardware version A.

Field upgradeable to 1.x software versions.

Enhancements

- Changed "Settings changed" alarm active time 30 → 60 s. (Shout 23948)

Fixes

- Internal changes not visible to end-user. (Shout 25997, 26003)

Version 1.0, released 19.6.2014 – First customer release

Compatibility

Compatible only with HDO907 hardware version A.